Report No. : HS1208290076A Version : A



JETTING WATER AND DUST TEST REPORT

Company : <u>Getac Technology Corporation</u>

Address : 5F., Building A, No. 209, Sec. 1, Nangang Rd., Nangang Dist.,

Taipei 11568, Taiwan, R.O.C.

Model Name : <u>Z710</u>

Date Received : AUG 29, 2012

Date Tested : <u>AUG 29, 2012 ~ AUG 30, 2012</u>

TESTING LABORATORY IS ACCREDITED BY:

IEC/IECQ 17025 certificate of independent test laboratory approval

Certificate No.: T1091

ISO 17025 accredited in respect of laboratory is approved by TAF

Certificate No.: L0835-090819

ISO 9001 certificate is approved by TUV CERT certification body of TUV NORD Cert GmbH

WE HEREBY CERTIFY THAT:

The test(s) shown in the attachment were conducted according to the indicating procedures. We assume full responsibility for the accuracy and completeness of these tests and vouch for the qualifications of all personnel performing them.

405405	Name	Signature	Date
Test Engineer	Gin Lu	Fin Lu	Sep 03, 2012
Manager	General Lee	Jerual	Sep 03, 2012

NOTE:

1. This report will be invalid if reproduced in part or altered in any way,

2. This report refers only to the specimen(s) submitted to test, and is in if used other

3. This report is ONLY valid with the examination seal and signature of the signature of th

 The tested specimen(s) will only be preserved for thirty days fro collected by the applicant.



Integrated Service Technology Inc.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiw an, R.O.C.

Tel: 886-3-578-2266, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1208290076A

Page 2 of 8

1. GENERAL INFORMATION

1.1 DESCRIPTION OF UNIT

Manufacturer: Getac Technology Corporation

Model name: Z710

Sample quantity: 1 unit

1.2 UNIT OPERATING CONDITION

None

INTEGRATED SERVICE TECHNOLOGY

Integrated Service Technology Inc.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiw an, R.O.C.

Tel: 886-3-578-2266, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1208290076A

Page 3 of 8

2. JETTING WATER TEST

2.1 TEST EQUIPMENT



- Internal diameter of the nozzle: 6.33mm
- Water flow meter
- Water pressure meter
- IEC/EN 60529 IPX5 standard

2.2 LABORATORY AMBIENCE CONDITION

Temperature: 25°C

Relative humidity: 33.5% (RH)

2.3 REFERENCE DOCUMENT

The test is based on IEC/EN 60529 IPX5 Jetting water Test Protected.

2.4 TEST CONDITION

Unit is non-operating.

Water flow: 12.5 I/minute
Water pressure: 0.3 bar

Distance from nozzle to unit: 2.5 meter

Duration of test: 6 minutes (1 minute for each face)

Orientation: Front, rear, top, bottom, left and right faces

2.5 SUMMARY OF TEST

After testing, visual inspection showed no water permeated into unit (the inner unit was dry) and function was normal.

INTEGRATED SERVICE TECHNOLOGY

Integrated Service Technology Inc.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiw an, R.O.C.

Tel: 886-3-578-2266, Fax: 886-3-610-0399

http://www.istgroup.com

3. DUST TEST

3.1 TEST EQUIPMENT

Model	Serial Number	Calibration Date
Vötsch-VDT 1000A	59566059640010	DEC 15, 2011

3.2 LABORATORY AMBIENCE CONDITION

Temperature: 23±3°C

Relative humidity: 55%±3% (RH)

3.3 REFERENCE DOCUMENT

The test is based on IEC/EN 60529 IP6X Dust Test Protected.

3.4 TEST CONDITION

Unit is non-operating.

Dust material: Talcum powder (100% dry fine)

Particle size	Amount (%)
< 5 µm (Diameter)	42.31%±5
5~10 μm (Diameter)	35.85%±5
10~20 μm (Diameter)	21.15%±5
20~40 µm (Diameter)	0.69%±5
> 40 µm (Diameter)	0%

Amount of talcum power: 2 kg/m³ (chamber volume)

Dust density: 2.03 g/cm³

Depression level: 10 mbar

Air direction: Vertically to achieve slowest possible downward settlement

Duration of exposure: 8 hours

3.5 SUMMARY OF TEST

After testing, visual inspection showed no dust particle permeated into unit and function was normal.

Report No.: HS1208290076A

Page 4 of 8